

Release Notes dryve D1

**Endless-Rotation (ROT) Direction Change**

In previous FW versions a certain possibility of direction changes with feedback controlled endless-rotation motions were present. This issue is fixed with the current FW version.

Load Current Error while Boot Up

The sporadic occurring error “E08 Drive Supply Low” is fixed due to a optimisation of the start-up routine. This error mainly occurred when using power supplies with a power output above 500 W.

General Optimisation

User Interface optimisation and additional improvements.

CANopen

Added communication via CANopen.

Implemented according to CiA 301 and CiA 402.

Modbus TCP

Added communication via Modbus TCP.

Implemented according to CiA 309.